IS 1489 (Part-1): 2015










## **Portland Pozzolana Cement** Despatched during Week No. 19 From 7-May-2022 13-May-2022 То Test Certificate No. 19 WCW/IMS/QA/FM/18 Reference No. Dated 18-Jun-2022 Results S.N. **Parameters** Requirement as per IS 1489 (Part I) : 2015 Obtained **Chemical Composition** Loss on Ignition (% by mass) 2.25 Not More than 5.0 % Not more than 6.0 % Magnesia (% by mass) 0.90 Sulphuric Anhydride SO3 (% by mass) 2.14 Not More than 3.5 % 1 Not more than 0.1 % for general purpose & not Chloride Content (% by mass) 0.01 more than 0.05 % for pre-stressed structures Not More than [X + 4.0 (100-X) / 100] & Not less than (0.6 X), Where "X" is the declared Insoluble Residue (% by mass) 24.66 Pozzolana content in cement **Physical Analysis** Fineness 2 Blaine's Specific Surface Area (m2 / kg) 335 Not Less than 300 **Compressive Strength (MPa)** Not less than 16.0 72 ± 1h (3 Days) 27.7 3 168 ± 2h (7 Days) 37.8 Not less than 22.0 672 ± 4h (28 Days) \* 53.9 Not less than 33.0 Setting Time (Minutes) 160 4 Initial Not less than 30 Final 235 Not more than 600 Soundness Not more than 10.0 5 Le-Chatelier Expansion (mm) 1.00 0.040 Auto-Clave Expansion (%) Not more than 0.8 Drying Shrinkage (%)\* 0.06 Not more than 0.15 6 Normal Consistency (%) 31.00 7 Temp. During Testing (0C) 27.00 (27 ± 2)0C

\* Fly Ash Content in Cement is (%)

The above cement complies with the requirements of IS 1489 (Part I): 2015 for Portland Pozzolana Cement.



Manager (QA)

DGM QC

Registered Office: Cement House, 121, Maharishi Karve Road, Mumbai - 400020

34.00